



Service Bulletin #75 SJB-46TK and SJB-66TK Solid State Relay Installation

March 28, 2000

Product Affected: SJB-46TK, SJB-66TK

SJB-46TK

94205 and below.

SJB-66TK

93433 and below.

Introduction:

To ensure the safety of our customers and yours, Skyjack requires the following retrofit be performed on the above listed machines. Please follow the instructions below to complete this service bulletin..

Tools Required:

- Blade Screwdriver
- Wire Cutter
- Wire Stripper
- Crimper
- 1 Kit (Hardware is in bottom of relay box.)

Procedure:

1. Turn battery disconnects switches to the off positions.
2. Open the platform control box.
3. Disconnect the four wires from relay 75CR. (39K on some older machines)
4. Remove relay 75CR. (39K)
5. Mount solid state relay to far left relay mounting hole using hardware removed from 75CR. (39K)
6. Cut terminals from wires.
7. Install ¼" fork terminals on wires 08 and 75A.(10 & 104 on older machines)
8. Install #6 fork terminals on wires 02 and 75.
9. Attach wires to solid state relay as follows:
 - a. Pin 1 Wire 08 (10)
 - b. Pin 2 Wire 75A (104)
 - c. Pin 3 Wire 75
 - d. Pin 4 Wire 02



10. Close platform control box.
11. Turn battery disconnects switches to the on positions.
12. Test functions.

Parts and Warranty Policy:

Upon completion, send in a warranty claim form, for each machine, stating Service Bulletin #75 has been completed.

Skyjack will pay ½ hour of labor plus travel time, up to 4 hours, for this bulletin.

Ownership of Machines:

If you have sold or transferred SJB-46TK or SJB-66TK machine(s) with the serial numbers listed above, it is your responsibility to forward this service bulletin to the current owner and to notify Skyjack Inc.

Contact Information:

We regret the inconvenience and appreciate your cooperation. If you have any questions please call Skyjack Service at **800-275-9522** or **630-262-0005**. You can e-mail any questions to service@skyjackinc.com